# OnePlus 3 Interconnect Cable Disconnect

Prerequisite guide only! Steps to disconnect the interconnect cables from the motherboard.

Written By: Arthur Shi

INTRODUCTION

Prerequisite guide only! Steps to disconnect the interconnect cables from the motherboard.

🔧 TOOLS:

- Phillips #00 Screwdriver (1)
- Spudger (1)

Step 1 — OnePlus 3 Interconnect Cable Disconnect

- Remove the 3 mm Phillips screw securing the cable bracket.

- Remove the cable bracket.

Step 2

- Use the point of a spudger to pry up and disconnect the interconnect flex cable from the motherboard, which is located above the battery.

- Repeat the process to disconnect the daughterboard flex cable from the motherboard.

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2020-11-28 07:16:19 AM (MST).