Shark ION Robot S87 Trash Tray Replacement

An easy guide to replace the trash tray of your Shark ION Robot S87.

Written By: Tommy Chang

This document was generated on 2020-11-28 07:55:20 AM (MST).

INTRODUCTION

Is your Shark ION Robot S87 throwing error messages or is there no suction anymore? The primary reason for these occurrences is a loose or faulty trash tray. This happens when the vacuum sucks large or pointed items. To fix this, change your trash tray or check if it is not secured. Here is an easy guide to fix it.

⚙ **PARTS:**

- Shark ION S87 Trash Tray (1)

This document was generated on 2020-11-28 07:55:20 AM (MST).

www.iFixit.com

Step 1 — Trash Tray

- Flip the Shark ION Robot so that the underside is facing up.

- Hold the button on the bottom of the vacuum, and slide the tray away from the device.

To reassemble your device, follow these instructions in reverse order.