iFIXIT

# MacBook Pro 15" Retina Display Early 2013 Airport wireless card Replacement

Replace your MBPr airport wireless -n card to new -ac card

Written By: Ender

This document was generated on 2020-11-17 05:55:53 AM (MST).

© iFixit — CC BY-NC-SA   www.iFixit.com   Page 1 of 3

Step 1 — MacBook Pro 15" Retina Display Early 2013 Airport wireless card Replacement


- Check your model number (written on back side of your mbpr) before buy a new wireless card. As per my mbp model, I ordered Broadcom [BCM94360CSAX](#) wireless ac and bluetooth 4.0

- You can learn your current PHY mode by holding "option" key and press wireless symbol on your screen.

Step 2

- BCM94331 CSAX

- BCM94360C

- You can remove and replace new card by the [guide](#) of this beautiful site :)

This document was generated on 2020-11-17 05:55:53 AM (MST).

Step 3

- Thats it. Now the connection becomes "ac" new card works perfectly

www.iFixit.com