Lenovo IdeaPad U430 Touch Charging Port Replacement

This guide shows how to replace the Charging Port for a Lenovo IdeaPad U430 Touch. After a recall on the charging port, this became a common replacement.

Written By: Patrick Ripkey

🔧 TOOLS:

- [Phillips #1 Screwdriver](#) (1)
- [Metal Spudger](#) (1)
- [iFixit Opening Tools](#) (1)

This document was generated on 2020-11-19 08:40:38 PM (MST).

www.iFixit.com

Step 1 — Bottom Cover

- Power off your computer before you begin.

- Find and remove the 10 Phillips style body screws on the bottom of the laptop case.

Step 2

- Remove 2 screws, 1 located on the left hinge cover and one located on the right hinge cover.

Step 3

- Starting from the front, use a plastic opening tool to separate the bottom of the case from the body of the laptop.

Step 4 — Charging Port

- Disconnect charging port from motherboard.

- To do this, press the spudger on the center dimple and push the connector out.

This document was generated on 2020-11-19 08:40:38 PM (MST).

© iFixit — CC BY-NC-SA | www.iFixit.com | Page 4 of 6

Step 5

- Pry the charging port out of the socket with a metal spudger.

- It may be necessary to pry from each side.

Step 6

- Remove charging port from laptop.

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2020-11-19 08:40:38 PM (MST).