



# Acer Aspire S3-391-6046 Fan Replacement

If your Acer Aspire S3-391-6046 ultrabook is...

Written By: Connor Talbot



# INTRODUCTION

If your Acer Aspire S3-391-6046 ultrabook is overheating, it might be a problem with the fan assembly. This is a guide for how to remove and replace it.

---

## TOOLS:

Phillips #1 Screwdriver (1)

Tweezers (1)


---

## Step 1 — Back Cover



- Place laptop upside down.

## Step 2



- Remove the twelve 5mm screws with a Phillips #1 screwdriver.

## Step 3



- Lift cover upwards away from you.



## Step 4 — Fan



- Unscrew the three screws with a Phillips #0 screwdriver.

## Step 5



- Use either your hands or the [tweezers](#) to gently peel back the tape.

## Step 6



⚠ Do not pull anything by the wires.

- Use the tweezers to gently pull the small black plug out.
- After the plug is out, you should be able to pull the fan assembly out.

---

To reassemble your device, follow these instructions in reverse order.