




# HP Media Center 876x TV Tuner Card Replacement

The HP Media Center 876x can utilize its TV...

Written By: Balakrishnan Pillai



# INTRODUCTION

The HP Media Center 876x can utilize its TV tuner card to receive television service, enhancing its versatility.

Should you encounter difficulty receiving adequate service, consider replacing the TV tuner card.

A TV tuner card functions as a television tuner, enabling computers to receive television signals. Additionally, many TV tuners serve as video capture cards, enabling the recording of television programs onto a hard disk similar to a digital video recorder (DVR).

Refer to the [HP Media Center 876x Troubleshooting](#) Guide if you come across any other issues.

---


## TOOLS:

Phillips #1 Screwdriver (1)

Phillips #0 Screwdriver (1)

---

## Step 1 — Side Panel



- Remove the two (9 mm) hand screws on the back panel.



## Step 2




- Place the tower on its side.
- Slide the side panel horizontally to detach, and pull upward to remove.

## Step 3 — TV Tuner Card



- Identify the TV tuner card (distal from the cooling fan, in the lower-left corner of the tower).
- Using a #0 Phillips head screwdriver, remove the one (6 mm) screw fastening the TV tuner card into its slot.

## Step 4



- Gently pull the card vertically out of its port.

To reassemble your device, follow these instructions in reverse order.