



KitchenAid Blender 5KSB52 Ultra Power hard rubber coupling Replacement

Kitchen Aid Hard Rubber Coupling for Mixer 5KSB52 Ultra Power. Replace the overcharged, low-performance coupling.

Written By: Froebel Christian



This document was generated on 2020-11-28 05:13:21 AM (MST).

INTRODUCTION

In this guide, we will show you how to replace an overcharged, low-performance hard-rubber coupling in a Kitchen Aid Mixer 5KSB52 UltraPower.

Step 1 — Hard rubber coupling



- Disconnect the blender from the power supply. Prepare tools and spare parts. Tools required: original spanner, small water pump tongs. Spare part: hard rubber coupling

Step 2



- Loosen the defective coupling with water pump tongs and original open-ended spanner. Hold the axis with an open-ended spanner and unscrew the coupling. Remove coupling.

Step 3



- Insert the new coupling and screw it on slightly. Screw the new coupling by hand with a spanner.

Step 4



- Finished.

Repeat the steps in reverse order to reassemble your device.