




Nokia X USB Port Replacement

How to replace USB port of Nokia X phone.

Written By: Josh Perino



INTRODUCTION

Is your Nokia X unable to connect to a USB charger? This guide will shows how to replace a faulty USB port.



TOOLS:


- [Spudger](#) (1)
 - [iFixit Opening Tools](#) (1)
 - [Soldering Iron](#) (1)
-

Step 1 — Nokia X Disassembly Prerequisites



- Remove the back cover of the device by applying light pressure toward the outer rim and display.

Step 2



- Remove 7 (size 4 M1 4*3.5) and 4(size 6 M2 6*4.5) screws using P5 hex screwdriver.
- The M2 screws are shown in red.
- The M1 screws are shown in orange.

Step 3



- Gently separate the display from the chassis.
- Slowly spread the display and chassis until the inside of the device is reachable.



⚠ Do not pull apart.

Step 4




- Using the [spudger](#) tool, release the top flex ribbon from the light swap package.

Step 5 — USB Port



- Again, using a spudger tool, release the rear facing camera from the light swap display.
- Carefully remove the light swap display from the chassis by applying pressure to the circuit board.

Step 6



- Using a soldering iron, desolder the broken USB port.
- Solder your replacement USB port onto the light swap package.

To reassemble your device, follow these instructions in reverse order.