



보관됨

iPad 2017 (5) LTE Glass Replacement

작성자: Tikhonovich Lab

A close-up photograph of a person's hand holding a black iPad. The screen is severely cracked and shattered, with large pieces of glass missing and the underlying display layer exposed. An orange semi-transparent banner is overlaid on the right side of the image, containing the text 'iPad 5 / Air / 2017 Glass Replacement' in white. The background is slightly blurred, showing a workshop or repair environment.

**iPad 5 / Air / 2017
Glass Replacement**

